

Memo

To: Amy Hodgen

Cc:

From: Julia Mardjuki

Date: 31 January 2019

Subject: PLN170703 – 626 Heidelberg Road (Village) – Section 72

Application – Open Space Referral

Dear Amy

I have reviewed the plans provided for the amended application for the Village Precinct within the Amcor Development, provided on 4/1/2019. Please find my comments below on the permit conditions related to landscaping.

Landscaping

17. Before the development commences, an amended Landscape Plan to the satisfaction of the Responsible Authority must be submitted to and approved by the Responsible Authority. When approved, the amended Landscape Plan will be endorsed and will form part of this permit. The amended Landscape Plan must be generally in accordance with the Landscape Plan prepared by Aspect Studios and dated 20 February 2018, but modified to include (or show):

No.	Permit condition	Notes
(a)	Consistency with the architectural	Provide latest architectural drawings on all
	drawings pursuant to Condition 1	landscape plans.
(b)	Greater detail of the vertical planting	This condition has been addressed with the
	proposed to the Living Edge regarding	drawing from Bird de la Coeur architects and
	plant species type, irrigation and	consultant advice note from Aspect dated
	maintenance details;	21/01/2019.
(c)	Greater detail of the steel inserts,	More information will need to be provided to
	including cross sections, demonstrating	assess this condition.
	that they will not be a tripping or	
	slipping hazard, or alternatively removal	
	of this feature.	
(d)	To Heidelberg Road:	
	(i) Minimum footpath width of 3m	Condition has been met.

	/ii) Domaya cantinyaya landacana strin	Condition has been met.
	(ii) Remove continuous landscape strip	
	(iii) Introduce bicycle hoops and seating	Condition has been met, however final
	between street trees;	locations to be verified and coordinated with
	(1) 2	Urban Design and Sustainable Transport.
	(iv) Retaining wall relocated at the kerb	Further levels across Heidelberg Road need to
	side edge	be provided to verify this condition.
	(v) Remove brick paving extending from	Condition has been met.
	the Outer Circle Mews	
		There is still a residual garden bed reflective of
		the outer circle mews style along Heidelberg
		Road. Our preference is to continue the tree
		planting along Heidelberg Road to create a
		strong boulevard of tree planting and remove
		the larger garden bed.
		Review the location of the bus stop and if it will
		impede access for emergency vehicles. Ensure
		final location is compliant with standards but
		meets access requirements.
	(vi) Tree species to consider impact	There is acknowledgement of this in the notes,
	from future location of power lines and	however further information is needed to
	infrastructure.	clarify this condition.
	(vii) Ensure/demonstrate the tree	Condition has been met.
	within the splitter island adjacent to the	
	vehicle entrance does not impact on	
	sight lines.	
(e)	To the outer circle mews:	
	(i)The cluster of four trees at each end	The four trees at each end have not been
	of the Mews to be replaced with a	removed, condition has not been met.
	single tree;	
		Information around tree species will need to be
		provided in order to assess this point.
	(ii) Avoid small 'left over; spaces	Condition has been met.
	between street furniture and garden	
	beds;	
	(iii) Small garden beds or vertical garden	WSUD beds have been provided in this
	planting along the eastern edge	location. Please provide further information on
		the system and its broader connections.
	(iv) Greater detail of the windscreens	More information will need to be provided to
	e.g. materials, porosity	assess this condition.
	(v) Provision of BMX coping/deterrents	More information will need to be provided to
	to street furniture	assess this condition.
	(vi) colour variation applied to the brick	More information will need to be provided
	plinths and pavements	around plinth details to assess this condition.
(f)	To the southern access lane:	
	(i) Further tree planting to the	Condition has been met, however discussions
	north/east edge (triangular space);	at the meeting on 13/11/18 around the use
		and layout of this space have not been
		reflected in these plans.
	(ii) Minimum 1.5m planting width for	Condition has been met.
	street trees	
		I .

	T	
	(iii) Doors to the back of house storage	Condition has been met, however
	area to not open outward to the	consideration will need to be made as to how
	footpath	sightlines to the lower ground level entry point
		are achieved.
(g)	To the Level 1 terrace:	lo mi
	(i) Provision of medium sized trees in	Condition has been met.
	larger planter boxes	
	(ii) Inclusion of softer materials	Condition has been met.
	(iii) Seating to be provided in clusters	Review layout of seating and potential for
		gathering and congregation in this area.
41.)		Further detail on seating to be provided.
(h)	To the Residential Gardens/Paper Trail	
	(i) Further tree planting along the	Condition has been met.
	southern and eastern edge of the	
	residential gardens	
(i)	To the Village Square	
	(i) Redesign to avoid significant change	Further information is required on levels and
	in level between the square and Latrobe	grading in order to assess the condition.
	Avenue	
	(ii) Provision of large trees along the	Condition was met, please provide
	western side that will allow light to	supplementary tree planting as per condition
	penetrate at ground level.	liii below.
	(iii) Incorporate landscaping on the	More information will need to be provided to
	eastern edge of the square that will	assess this condition.
	supplement the Main Street tree	
	planting	
	(iv) Replace corten seel with an	This condition has not been met.
	alternative graffiti resistant material to	More corten steel elements have been added
	the satisfaction of the Responsible	as landscape features.
	Authority	We will need more information how these
		features sit within the Village Square, how they
		will be incidentally used and how they
	(A) Additional action and the P	complement the space.
	(v) Additional entrance that aligns with	More information will need to be provided on
	the Latrobe Avenue crossing	the plan in order to assess this condition.
	(vi) Deletion of ground water jets	Condition has been met.
	(vii) Consider custom seating that allows	More information will need to be provided to
	for groups to gather and interact	assess this condition.
	(viii) Lawn area to be raised on two	Condition has been met, however ongoing
	sides to deter cross traffic movements	maintenance access to the lawn area will need
	(in) Discola has an add the first for the	to be considered.
	(ix) Bicycle hoops, drinking fountains	Details to be provided.
	and bins to Council's Standards or	
	otherwise to the satisfaction of the	
	Responsible Authority;	Ladrata la salta de Companyo d
	(x) Provision of clear wayfinding signage	Indicate location of signage on landscape plans
	for access to Level 1	as per 'Wayfinding and Interpretation Strategy
	/ 3/B : 14 : 24 : 14 : 1	Report'.
	(xi) Double sided timber benches to	More information will need to be provided on
	include backs and armrests; and	the plan in order to assess this condition.

(xii) Clear demarcation between public	More information will need to be provided on
and private areas; including location of	the landscape plans in order to assess this
assets	condition.

An Irrigation Management Plan will need to be provided to satisfy condition 18.

Conditions 19 and 20 can only be assessed once works are complete.

Include notes on maintenance and landscape specifications prior to works in future landscape drawings to supplement condition 20.

Please feel free to contact me if you would like me to clarify any of these points.

Sincerely

Julia Mardjuki

Open Space Planner