

## Amcor Riverbank Inspection

Created	2021-02-15 22:55:01 UTC
Updated	2021-02-15 23:12:36 UTC
Location	-37.785909, 145.0287445
Title/Address	Amcor Riverbank Inspection
Date	2021-02-16

### 0

Distance (m)	0
--------------	---

### Photos








---

15

Distance (m)

15

Photos






30

Distance (m)

30

Photos





---

40

Distance (m)

40

Photos









---

Additional Notes

Ground movement and displacement

---

**50**

Distance (m)

50

---

Photos







---

60

Distance (m)

60

Photos







---

70

Distance (m)

70

Photos









---

80

Distance (m)

80

Photos







Additional Notes

Ground water seepage

Photos







---

**100**

Distance (m)

100

Photos





110

Distance (m)

110

Photos







16 Feb. 2021 10:09:43 am  
1A View Street  
Alphington  
City of Yarra  
Victoria



16 Feb. 2021 10:09:49 am  
1A View Street  
Alphington  
City of Yarra  
Victoria

---

120

Distance (m)

120

Photos





130

Distance (m)

130

Photos





---

140

Distance (m)

140

Photos





---

**150**

Distance (m) 150

---

**160**

Distance (m) 160

---

Photos



16 Feb. 2021 10:12:14 am  
8 Chandler Highway  
Kew  
Boroondara City  
Victoria



16 Feb. 2021 10:12:19 am  
8 Chandler Highway  
Kew  
Boroondara City  
Victoria





16 Feb. 2021 10:12:24 am  
8 Chandler Highway  
Kew  
Boroondara City  
Victoria